

PUBLIC NOTICE

Intertek Warns of Unauthorized ETL Certification Mark on Epica Model 82473 Milk Frother

Published: August 6, 2018

The following is a notification from Intertek that the Epica Milk Frother identified below bears unauthorized Intertek Certification Marks for the United States and Canada. The products have not been evaluated by Intertek and it is not known if they comply with any safety requirements.

| | |
|----------------------------|---|
| Product Description | <i>Epica Milk Frother, Model 82473</i> |
| Manufacturer | <i>Unknown</i> |
| Number of Units | <i>Unknown</i> |
| Identification | <p><i>On Product: .ETL_{us} certification mark with Control Number 4004075, with the following</i></p> <ul style="list-style-type: none"> • <i>Brandname: Epica</i> • <i>Model 82473</i> • <i>Conforming to UL Standard 982 & 1082</i> • <i>Conforming to CSA Standard C.22.2</i> <ul style="list-style-type: none"> ○ <i>No. 1553.1</i> ○ <i>No. 1335.2.14</i> ○ <i>No. 1335.2.15</i> <p><i>See also product photos below.</i></p> |
| Reported Hazards | <i>Unknown</i> |
| Sold at | <i>Unknown</i> |
| What to do | <i>Products should not be used and returned to the point of purchase. Distributors and retailers should discontinue sales and return all inventories to their supplier.</i> |

Product Photographs and Nameplate

