



Total Quality. Assured.

545 E Algonquin Road, Suite H
Arlington Heights, IL 60005 USA

Telephone: 847-439-5667
intertek.com

Published: 04-Mar-24
Revised:

Public Notice ID: 2024-04
Page 1 of 2

Counterfeit Intertek Certified Product Notification / Notification de produit certifié Intertek contrefaite

Landscape Luminaires / Luminaires paysagers

Notification Type:	Counterfeiting / Contrefaçon
Certification Type:	Not Intertek Certified

Notification

Intertek notifies consumers, retailers and distributors that we have been made aware of counterfeit Intertek Test Reports in the marketplace claiming products have been tested by Intertek. / Intertek informe les consommateurs, les détaillants et les distributeurs que nous avons été informés des contrefaçons Intertek Test Reports sur le marché revendiquant des produits ont été testés par Intertek.

Company Identification

ABBA Lighting USA

Product Identification

Counterfeit document of a Authorization to Mark (ATM), ATM Issued: 15-May-2017, ABBA Lighting USA, Model(s): FLA01, FLB01, FLA02, FLB02, PLA01, PLB01, PLA02, PLB02, PLA03, PLB03, SPA01, SPB01, SPA02, SPB02, SPA04, SPB04, SPA05, SPB05, SPA03, DLA01, DLB01, STA01, STB01, STA02, STB02, STA03, STB03, STA04, STB04, STB05, STB06, STB07, WLA01, WLB01, WLA02, WLB02, WLA03, WLB03. WLA04, WLB04, WLB07, ULB01, ACB01, ATM for Report 161200887SHA-001, Control Number 3065607.

Document contrefait d'une autorisation de marquage (ATM), ATM émis : 15 mai 2017, ABBA Lighting USA, modèle(s) : FLA01, FLB01, FLA02, FLB02, PLA01, PLB01, PLA02, PLB02, PLA03, PLB03, SPA01, SPB01, SPA02, SPB02, SPA04, SPB04, SPA05, SPB05, SPA03, DLA01, DLB01, STA01, STB01, STA02, STB02, STA03, STB03, STA04, STB04, STB05, STB06, STB07, WLA01, WLB01, WLA02, WLB02, WLA03, WLB03. WLA04, WLB04, WLB07, ULB01, ACB01, ATM pour le rapport 161200887SHA-001, numéro de contrôle 3065607.

Hazard Involved

Not certified by Intertek / Non certifié par Intertek

What To Do

Use of these products should be immediately discontinued and return to the point of purchase. Distributors and retailers should discontinue sales and return inventories to their suppliers. / L'utilisation de ces produits doit être immédiatement abandonnée et retourner au point d'achat. Les distributeurs et les détaillants doivent cesser les ventes et retourner les inventaires à leurs fournisseurs.



Total Quality. Assured.

545 E Algonquin Road, Suite H
Arlington Heights, IL 60005 USA

Telephone: 847-439-5667
intertek.com

Published: March 4, 2024
Revised:

Public Notice ID: PN 2024-04
Page 2 of 2

Photos and Images / Photos et images

COUNTERFEIT DOCUMENT



AUTHORIZATION TO MARK

This authorizes the application of the Certification Mark(s) shown below to the models described in the Product(s) Covered section when made in accordance with the conditions set forth in the Certification Agreement and Listing Report. This authorization also applies to multiple listed model(s) identified on the correlation page of the Listing Report. This document is the property of Intertek Testing Services and is not transferable. The certification mark(s) may be applied only at the location of the Party Authorized To Apply Mark.

Applicant: ABBA Lighting USA	Manufacturer: Nantong Pantech Electrical Co. Ltd.
Address: 7751 Alabama Avenue Los Angeles CA 91304	Address: 52 W. Jiatong Road Cha He Rudong, Jiangsu China
Country: USA	Country: China
Contact: David Liu	Contact: Hong Jian Guo
Phone: 1(800) 360-2960	Phone: 086-513-8431198
FAX: (951) 360-5329	FAX: 086-513-84311011
Email: AbblightingUSA@gmail.com	Email: NA
Party Authorized To Apply Mark: Same as Manufacturer	
Report Issuing Office: Intertek Testing Services Shanghai Limited	
Control Number: 3065607	 for Dean Davidson, Certification Manager



This document supersedes all previous Authorizations to Mark for the noted Report Number.

This Authorization to Mark is for the exclusive use of Intertek's Client and is provided pursuant to the Certification agreement between Intertek and its Client. Intertek's responsibility and liability are limited to the terms and conditions of the agreement. Intertek assumes no liability to any party, other than the Client, in connection with the agreement, for any loss, expense or damage considered by the use of this Authorization to Mark. Only the Client is authorized to permit copying or distribution of this Authorization to Mark and the Client is solely responsible for any misuse of Intertek's Certification mark is restricted to the conditions laid out in the agreement and in this Authorization to Mark. Any further use of the Intertek logo for the sale or advertisement of the listed material, product or service must first be approved in writing by Intertek. Initial Factory Assessments and follow up services are for the purpose of assuring appropriate usage of the Certification mark in accordance with the agreement, they are not for the purpose of production quality control and do not release the Client of their obligations in this regard.

Intertek Testing Services NA Inc.
545 East Algonquin Road, Arlington Heights, IL 60005
Telephone 800-345-5851 or 847-439-5667 Fax 312-201-1672

Standard(s):	UL 1838 Issued: 2003/01/13 Ed: 3 Rev: 2015/01/13 Low Voltage Landscape Lighting Systems CSA C22.2 No.250.7 Issued: 2007/11/01 Ed.1 (R2012) Extra-low-voltage Landscape Lighting Systems; Gen. Inst. No. 1: 2008
Product:	Landscape luminaires
Models:	FLA01, FLB01, FLA02, FLB02, PLA01, PLB01, PLA02, PLB02, PLA03, PLB03, SPA01, SPB01, SPA02, SPB02, SPA04, SPB04 , SPA05, SPB05, SPA03, DLA01, DLB01, STA01, STB01, STA02, STB02, STA03, STB03, STA04, STB04, STB05, STB06, STB07, WLA01, WLB01, WLA02, WLB02, WLA03, WLB03, WLA04, WLB04, WLB07, ULB01, ACB01